
Progressive Mercury/040 Jumper Update: 3000T

We have recently determined that the manual for the Progressive Mercury/040 is incorrect concerning the jumpering of the 3000T. Field testing has revealed that the board works perfectly without changing or adding any jumpers, despite section 2.1.4 in the Users Manual. While our jumper settings do not appear to change the performance of the system, we do recommend resetting the system's jumpers to avoid future conflicts. Please follow these procedures:




NOTE: Some users have taken to changing jumpers other than what we've suggested. This may change internal system timings that can lead to lockups, non-validated harddisks and floppies and complete systemwide failures. PP&S strongly suggests that you restore the jumpers to the default settings (as in the diagram) before serious data failure occurs.



Progressive Mercury/040 GAL Update: 030 Boot Conflict

We have found that some early-release Progressive **Mercury/040** boards do not boot directly to the 68040, but rather to the native 68030 of the Amiga 3000's motherboard. This can happen on the first power-up or as a warm reboot. We have isolated this problem as being in a GAL chip on the **Mercury/040** in socket U301, and we recommend this chip change to alleviate the problem:




	L	REMOVE	the chip gently using a chip removal tool, or a small flat-tip screwdriver.
CHIP U301 LATTICE GAL 22v10B-10LP		INSERT	the replacement Texas Instruments chip gently into the U301 socket, Take care that the notch in the chip orients to the left (as shown) and that the pins do not bend underneath the chip during installation.
]	INSTALL	in system as usual. The Mercury/040 will now always cold-boot into the 68040 mode, as expected. This will not affect the ability of Mercury/040 to switch between 040 and 030 modes.
		REPLACE	the original Lattice GAL chip in the protective foam block provided with the replacement GAL, and send it back to Progressive. This MUST be done to avoid being charged for the update.

After inserting the replacement GAL, the Progressive **Mercury/040** will operate normally under the Workbench 2.0 operating system. Please send the Lattice GAL to:

PROGRESSIVE464 Kalamath Street**PERIPHERALS**Denver, Colorado 80204**ATTN:** GAL RETURN

MERCURY SUPPLEMENTARY JUMPER SETTINGS



Amiga Hardware World Everything about Amiga hardware...

> ~ http://amiga.resource.cx